

C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0366 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

May 24, 2007

Stephenie Ellwood, Administrator Gables Special Needs I 840 1st Street Idaho Falls, ID 83401

License #: RC-858

Dear Ms. Ellwood:

On March 1, 2007, a life safety code survey was conducted at Gables Special Needs I - Gables Management, LLC. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

TB/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

March 6, 2007

Mark Stephenson, Administrator Gables Special Needs I 840 1st Street Idaho Falls, ID 83401

Dear Mr. Stephenson:

On March 1, 2007, a life safety code survey was conducted at Gables Special Needs I - Gables Management, LLC. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by March 31, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED 01 - BUILDING 1 A. BUILDING B. WING 13R858 03/01/2007 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER

GABLES SPECIAL NEEDS I 840 1S1			FALLS, ID 83401			
X4) ID REFIX TAG	SUMMARY STATEMENT OF DEFICIENCII (EACH DEFICIENCY MUST BE PRECEDED B' REGULATORY OR LSC IDENTIFYING INFORM	/ FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLET DATE	
R 000	Initial Comments The facility was found to be in substant compliance with the fire and life safety requirements of the Rules for Resident Assisted Living Facilities in Idaho. No deficiencies were cited during the standfire/life safety survey conducted on Mar 2007. The surveyor conducting the survey was Taylor Barkley Health Facility Surveyor Facility Fire safety & Construction	ial or ore dard rch 01,	R 000	DEFICIENCY)		

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

Facility Name	Physical Address	Phone Number
Gables Special NEEDS I	840 1st Street	(908) 255-5H89
Administrator	City	ZIP Code
MAYIK STEPHENSON	Idaho Falls	83401
Survey Team Leader	Survey Type	Survey Date
TAYLOR BANKLEY		3-1-7
NON-CORE ISSUES		

$M_{\rm M}$	DYK ST	ephenson	Idaho Falls	83401	
Survey T	eam Leader		Survey Type	83401 Survey Date	
TR	VORE ISSU	erkley		3-1-7	7
		ES /			
ITEM #	RULE # 16.03.22	上上上的。 电自用的时间 电影 医上颌 电影 化二甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基	DESCRIPTION		DATE BFS RESOLVED USE
1	405.05	The mechanical room	in the laundry room has s	everal	
		pipe penetrations in	v the ceiling.	***************************************	
7	0 E 0 02	a Carilla I -		•	0 2 2 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2
. لم	730,01	A. The Ancility has	Three Steps leading into	i And	**************************************
		steps are nort	three steps leading into cility without handrails. The of building egress.	,626	· 电多级图表 \$\frac{1}{2}
		B. Resident room # 1	1 is missing the toilet sea	т.	· · · · · · · · · · · · · · · · · · ·
					25 6 5 7 5 6 5 6 5 6 5 6 5 6 5 6 5 6 5 6

20	a Danuing d Date	Clarabase of Facility Days			
•	e Required Date	Signature of Facility Representative			Date Signed 4-1-C7